



उपविभागीय अभियंता
सार्वजनिक बांधकाम उपविभाग, श्रीगोंदा.
श्रीगोंदा-दोंड रस्ता, ता. श्रीगोंदा, जि. अहिल्यानगर ४१३७०१
दूरध्वनी क्रमांक. (०२४८७) २२२३२७ Email : shrigonda.de@mahapwd.gov.in



जा.क्र.रेशा/३३८/सन २०२६

दिनांक. २३/०४/२०२६

प्रति,

✓ कार्यकारी अभियंता,
सार्वजनिक बांधकाम विभाग,
अहिल्यानगर

विषय :- इमारत सुस्थितीत असलेबाबत प्रमाणपत्र मिळणेबाबत

संदर्भ -

१. प्राचार्य, शिवाजीराव नागवडे डफोडिल्स स्कूल, श्रीगोंदा यांचे पत्र क्र. S.N.D.S./२७४/२०२५-२६ दि.३०/०३/२०२६
२. श्री. स्वप्नील तनपूरे, यांचा दि.२०/०४/२०२६ रोजीचा Structural Stability अहवाल
३. श्री.जी.बी.गुर्जर कनिष्ठ अभियंता यांचा दि.२१/०४/२०२६ रोजी चा अहवाल

उपरोक्त विषयास अनुसरून प्राचार्य, शिवाजीराव नागवडे डफोडिल्स स्कूल, श्रीगोंदा यांनी श्रीगोंदा येथील गट क्र.११२०/१अ/१/१ मधील तुळजाभवानी सेवा प्रतिष्ठाणची इमारत- शिवाजीराव नागवडे डफोडिल्स स्कूल, श्रीगोंदा ही शैक्षणिक इमारत वापरासाठी सुस्थितीत असलेबाबतच्या प्रमाणपत्राची मागणी संदर्भित पत्रान्वये केलेली आहे.

त्यानुसार संदर्भ क्र.२ अन्वये श्री. स्वप्नील तनपूरे, यांनी त्यांचा दि. २०/०४/२०२६ रोजीचा Structural Stability अहवाल या कार्यालयास सादर केलेला आहे त्यास अनुसरून संदर्भ क्र.३ अन्वये श्री.जी.बी.गुर्जर कनिष्ठ अभियंता यांनी सदर इमारतीची प्रत्यक्ष पाहणी करून इमारतीत किरकोळ लिकेज व प्लॅस्टर दुरुस्ती करणे आवश्यक असल्याचे व दुरुस्ती नंतर इमारत वापरण्यायोग्य व सुस्थितीत असलेबाबतचे कळविले आहे त्यानुसार सदर प्रमाणपत्र प्रतिस्वाक्षरीसाठी यासोबत सादर करण्यात येत आहे. हे आपले माहिती व पुढील कार्यवाहीस्तव सविनय सादर.

सोबत : प्रमाणपत्र व Structural Stability अहवाल


उपविभागीय अभियंता
सार्वजनिक बांधकाम उपविभाग
श्रीगोंदा

BUILDING SAFETY CERTIFICATE

No. DB /BSC/ /2026

Date:- / /2026

Certified that the existing building Shivajirao Nagawade's Daffodils School, Shrigonda, Tal. Shrigonda, Ahilyanagar (name of the building or premises) Tal. Shrigonda, Dist. Ahilyanagar is having block (s) /Floor (s) as per details below:

Detail of Block (s) in school	Block (1)
No. of Floor (s) in the block	03

The building is owned/occupied by Shivajirao Nagawade's Daffodils School, Shrigonda, Tal. Shrigonda, Ahilyanagar (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the concerned Structural Consultant (Swapnil M. Tanpure, Ahilyanagar) and the building was visually inspected from our office Staff person (Shri. G. B. Gurjar, Jr. Engineer) of Public Works Sub Division, Shrigonda (Name of Department/ Govt.) on Date 21/04/2026 (Date of inspection) in the presence of Principal, Shivajirao Nagawade's Daffodils School, Shrigonda, Tal. Shrigonda, Ahilyanagar (Name and addresses of the Manager / Secretary or his representative) and that the building /premises are fit for occupancy for running school with effect from 22/04/2026 for a period of 1 (One) Year in accordance with rule and subject to compliance of the specific conditions as appended.

1. External surface plaster cracks at some areas were observed during the visual inspection of the building.
2. Plastering to some areas needs to be done immediately. Trees to be removed from walls immediately.
3. Leakages to external wall near toilet area and to balcony of third floor were seen so waterproofing and plastering to concerned area needs to be done immediately.
4. Exposure to the reinforcement in parapet wall was seen, Hence proper remedies to be made in this concern.
5. This certificate is given on the basis of document submitted by the school, Structural stability Certificate given by Mr. Swapnil M. Tanpure, Consulting Structural Engineer Ahilyanagar and reported by the technical staff of this office.
6. This considers that execution was done by the institute strictly as per designs and relevant code provisions.
7. If any differences in designs and relevant code provisions this certificate shall stand cancelled.

Issued on / /2026 at Ahilyanagar by Executive Engineer, Public Works Division, Ahilyanagar

COUNTER SIGNED


Sub-Divisional Officer,
P.W. Sub-Division,
Shrigonda

Executive Engineer,
Public Works Division,
Ahilyanagar